

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

Name of the School

St Marys Leuca LP School

1. Name of the Officer
2. Location
3. Period for which the certificate is issued
4. Types of building
5. Nature of defect if any
 - a) Foundation and basement
 - b) Superstructure
 - c) Doors and windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks if any)
6. Any Major defects notices which will render the building unsafe in any manner
7. Whether maintenance works have been done properly
8. Whether the structure is sound or not for conducting classes

Bindu Prasad - 8
Chesthala, Thuvavoor
2024 - 25
1) 2 x 12.6 x 6.6 x 3m
2) 3 x 16 x 6.7 x 3m
3) 2 x 8.8 x 4.8 x 3m
4) 2 x 8.8 x 4.8 x 3m

Nil

Nil

Yes

Sound under normal weather condition

Note:- 1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc.
2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

CERTIFICATE

Certified that the School was inspected by me on 13.05.2024
and found to be fit / unfit to conduct classes for the period 2024-25
for the reason stated above.

Place: Thyattussery
Date: 20.05.2024



[Signature]
Assistant Engineer

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

Name of the School : St Marys Leuca Senior Sec. School

1. Name of the Officer : Bindu Prasad. S
2. Location : Chesthala, Thuzuvoo
3. Period for which the certificate is issued : 2024 - 25
4. Types of building : GF 8x6.5x6.5x3.6m
FF 4x6.5x6.5x3.6m
SF 2x6.65x6.5x3.6m
Lab 2x9.85x6.5x3.6m
Library 1x6.6x6.5x3.6m
5. Nature of defect if any
a) Foundation and basement } Nil
b) Superstructure }
c) Doors and windows }
d) Wood work wrought and put up }
e) Roof }
f) Flooring }
g) Miscellaneous (Cracks if any) }- 6. Any Major defects notices which will render the building unsafe in any manner : Nil
- 7. Whether maintenance works have been done properly : Yes
- 8. Whether the structure is sound or not for conducting classes : Sound under Normal weather condition

Note:- 1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc.
2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

CERTIFICATE

Certified that the School was inspected by me on 13.05.24
and found to be fit / unfit to conduct classes for the period 2024 - 25
for the reason stated above.

Place: Thycattusseri

Date: 20.05.2024



[Handwritten signature]